

Equipment details

Customer: Bergen Brannvesen AS
Producer: Interspiro
Serial no: OL4909 / 10
Service interval: 24 months
Location: Bergen Brannvesen
Model: Cylinder
Build year: 2015

Data

Cylinder type: Steel
Color: white
Cylinder volume: 4.0
Oxygen cleaned: No
Working pressure (bar): 300
Test pressure (bar): 450
Application type: Diving
Test facility number: D79
Weight (kg): 5.60
Thread type: M18
Hydro tested: 05/2026

Exterior

|               |      |                        |      |
|---------------|------|------------------------|------|
| Heat damage   | Pass | Weight                 | Pass |
| Repainted     | No   | Line corrosion         | Pass |
| Hammer test   | Pass | Exterior condition     | Pass |
| Odor          | Pass | Minimum wall thickness | Pass |
| Dent or bulge | Pass | Exterior approved      | Pass |

Interior

|                                   |      |                          |      |
|-----------------------------------|------|--------------------------|------|
| Interpreted (thread verification) | Pass | Amount of loose material | Pass |
| Threads approved                  | Pass | Pitting corrosion depth  | Pass |
| Crack formation                   | Pass | Interior approved        | Pass |
| Sealing surface damaged           | Pass |                          |      |

Pressure testing

|                   |      |                                   |      |
|-------------------|------|-----------------------------------|------|
| Water temperature | Pass | PU (test pressure reached)        | Pass |
| Water fill (in)   | Pass | PU% (percentage of test pressure) | Pass |
| Water drain (out) | Pass | Pressure testing approved         | Pass |

Valve

|                       |      |                           |      |
|-----------------------|------|---------------------------|------|
| Overhauled            | No   | Filling connection thread | Pass |
| Valve/cylinder thread | Pass |                           |      |



General

|                     |    |                             |      |
|---------------------|----|-----------------------------|------|
| Repairs on cylinder | No | Cylinder and valve approved | Pass |
|---------------------|----|-----------------------------|------|

Technician

Serviced by: Daniel Kristensen

Signature  
*Daniel Kristensen*

