

CYLINDER HYDRO TEST

Certificate no: DSC-2026-000727

Service date: 27.05.2026

Valid until: —

Result: **Rejected**

Equipment details

Customer: Bergen Brannvesen AS
Producer: Luxfer
Serial no: M722936
Service interval: 24 months

Location: Bergen Brannvesen
Model: Vest flaske
Build year: 2018

Data

Cylinder type: -	Color: -	Cylinder volume: -
Oxygen cleaned: -	Working pressure (bar): -	Test pressure (bar): -
Test facility number: -	Weight (kg): -	Thread type: -
		Application type: -
		Hydro tested: -

Exterior

Heat damage	-	Weight	-
Repainted	-	Line corrosion	-
Hammer test	-	Exterior condition	-
Odor	-	Minimum wall thickness	-
Dent or bulge	-	Exterior approved	-

Interior

Interpreted (thread verification)	-	Amount of loose material	-
Threads approved	-	Pitting corrosion depth	-
Crack formation	-	Interior approved	-
Sealing surface damaged	-		

Pressure testing

Water temperature	-	PU (test pressure reached)	-
Water fill (in)	-	PU% (percentage of test pressure)	-
Water drain (out)	-	Pressure testing approved	-

Valve

Overhauled	-	Filling connection thread	-
Valve/cylinder thread	-		



General

Repairs on cylinder - Cylinder and valve approved -

Technician

Serviced by: Daniel Kristensen

Signature
Daniel Kristensen

