

CYLINDER HYDRO TEST

Certificate no: DSC-2026-000752

Service date: 03.06.2026

Valid until: 03.06.2027

Result: **Approved**

Equipment details

Customer: DS Bergen
Producer: AXSUB
Serial no: na
Service interval: 24 months

Location: valsmoget
Model: Depthsensor
Build year: -

Data

Cylinder type: - Color: - Cylinder volume: 0.4
Oxygen cleaned: - Working pressure (bar): - Test pressure (bar): - Application type: -
Test facility number: - Weight (kg): 12.50 Thread type: - Hydro tested: -

Exterior

Heat damage	Pass	Weight	Pass
Repainted	-	Line corrosion	Pass
Hammer test	Pass	Exterior condition	Pass
Odor	Pass	Minimum wall thickness	Pass
Dent or bulge	Pass	Exterior approved	Pass

Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Interior approved	Pass
Sealing surface damaged	Pass		

Pressure testing

Water temperature	Pass	PU (test pressure reached)	Pass
Water fill (in)	Pass	PU% (percentage of test pressure)	-
Water drain (out)	Pass	Pressure testing approved	Pass

Valve

Overhauled	-	Filling connection thread	Pass
Valve/cylinder thread	Pass		



General

Repairs on cylinder - Cylinder and valve approved Pass

Technician

Serviced by: Daniel Kristensen

Signature
Daniel Kristensen

