

CYLINDER HYDRO TEST

Certificate no: DSC-2026-000244

Service date: 26.01.2026

Valid until: 26.01.2027

Result: **Approved**

Equipment details

Customer: Bergen Sjøfartsmuseum
Producer: Interspiro
Serial no: UU1531
Service interval: 24 months

Location: Bergen Sjøfartsmuseum
Model: Cylinder
Build year: 2020

Data

Cylinder type: 2x6L twin	Color: white	Cylinder volume: 6.0
Oxygen cleaned: -	Working pressure (bar): -	Test pressure (bar): -
Test facility number: -	Weight (kg): -	Thread type: -
		Application type: -
		Hydro tested: -

Exterior

Heat damage	Pass	Weight	Pass
Repainted	Yes	Line corrosion	Pass
Hammer test	Pass	Exterior condition	Pass
Odor	Pass	Minimum wall thickness	Pass
Dent or bulge	Pass	Value: 3,7	
		Exterior approved	Pass

Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Interior approved	Pass
Sealing surface damaged	Pass		

Pressure testing

Water temperature	Pass	PU (test pressure reached)	Pass
Water fill (in)	Pass	PU% (percentage of test pressure)	Pass
Water drain (out)	Pass	Pressure testing approved	Pass

Valve

Overhauled	Yes	Filling connection thread	Pass
Valve/cylinder thread	Pass		



CYLINDER HYDRO TEST

Certificate no: DSC-2026-000244

Service date: 26.01.2026

Valid until: 26.01.2027

Result: **Approved**

General

Repairs on cylinder

Yes

Cylinder and valve approved

Pass

Technician

Serviced by: Daniel Kristensen

Signature

Daniel Kristensen

