

CYLINDER HYDRO TEST

Certificate no: DSC-2026-000248

Service date: 26.01.2026

Valid until: 26.01.2027

Result: **Approved**

Equipment details

Customer: IMC Diving AS
Producer: Interspiro
Serial no: 47878
Service interval: 24 months

Location: 257
Model: Cylinder
Build year: 2002

Data

Cylinder type: 2 x 3,4L Color: Composite Cylinder volume: 3.4
Oxygen cleaned: - Working pressure (bar): - Test pressure (bar): - Application type: -
Test facility number: - Weight (kg): - Thread type: - Hydro tested: -

Exterior

Heat damage	Pass	Weight	Pass
Repainted	-	Comment: 2,45kg	
Hammer test	Pass	Line corrosion	Pass
Odor	Pass	Exterior condition	Pass
Dent or bulge	Pass	Minimum wall thickness	-
		Exterior approved	Pass

Interior

Interpreted (thread verification)	Pass	Amount of loose material	-
Threads approved	Pass	Pitting corrosion depth	-
Crack formation	-	Interior approved	Pass
Sealing surface damaged	Pass		

Pressure testing

Water temperature	Pass	PU (test pressure reached)	Pass
Water fill (in)	Pass	PU% (percentage of test pressure)	Pass
Water drain (out)	Pass	Pressure testing approved	Pass

Valve

Overhauled	-	Filling connection thread	Pass
Valve/cylinder thread	-	Comment: 300Bar	



CYLINDER HYDRO TEST

Certificate no: DSC-2026-000248

Service date: 26.01.2026

Valid until: 26.01.2027

Result: **Approved**

General

Repairs on cylinder

- Cylinder and valve approved

Pass

Technician

Notes: twin set

Serviced by: Daniel Kristensen

Signature

Daniel Kristensen

