

BAILOUT 1.STAGE

Certificate no: DSC-2026-000576

Service date: 26.08.2025

Valid until: 26.08.2026

Result: **Approved**

Equipment details

Customer: Samba Marin AS
Producer: Aqualung
Serial no: M087519
Service interval: 12 months

Location: Fox Inspector
Model: Core / Helix
Build year: -

NOTE

Tested with Labtec PRO

This is a certificate confirmation, the documentation has a separate file.

Technician

Serviced by: Daniel Kristensen

Signature



workshop: DS BERGEN AS		person:	Daniel Kristensen
street: Storebotn 55G		phone:	91649162
place: 5309 Kleppestø		fax:	
		email:	Daniel@dsbergen.no
customer: Samba Marin		person:	An-Magridd
street: Røtingavegen 4		phone:	91841270
place: 5216 Søre Øyane		fax:	
		email:	Foxinspector@sambamarin.no
device data:	deadlines:	device-info:	service:
device no: M087519	1 y test 26.08.2026 1 y srv 26.08.2026		- 1 year service - cleaning and disinfection
type: Aqualung Core			
class: diving system basic			
location: Fox inspector			

Bailout reg set, New hoses and gauge, New OPV.

tests/measurements	unit	min	max	actual	result
visual test (0 = ok) input mask: (0 = classic, > 0 = extended/list...)			0	0	OK
HP leakage at max pressure after 0,5 min	bar	-5		-1	OK
demand valve opening pressure	bar	12	25	14,8	OK
static medium pressure at 200 bar cylinder pressure	bar	8	10,5	9,8	OK
MP leakage after 0,5 min at 200 bar lmt. 1 0=rel.1=abs. pulse	bar		10,5	9,9	OK
pressure comparison at 200 bar	bar	-10	10	2	OK
pressure comparison at 60 bar	bar	-10	10	1	OK
pressure release of test equipment (HP, MP and LP)				0	OK

test executed: 26.08.2025 16:07
 by: Daniel Kristensen

result:

test signed: 26.08.2025 16:08
 by: Daniel Kristensen

device ready for use

Lab.Net Profi V: 2024.0.0.0

next test on: 26.08.2026