

| | | | |
|---|---|---------------------|--|
| workshop: DS BERGEN AS | | person: | Daniel Kristensen |
| street: Storebotn 55G | | phone: | 91649162 |
| place: 5309 Klippestø | | fax: | |
| | | email: | Daniel@dsbergen.no |
| customer: Otech Marine Services AS | | person: | Stefan |
| street: | | phone: | 48608560 |
| place: Ågotnes | | fax: | |
| | | email: | sts@otech.no |
| device data: | deadlines: | device-info: | service: |
| device no: 2270500413 | 1 y test 11.02.2027 1 y srv 11.02.2027 | | - 1 year service - cleaning and disinfection |
| type: Scubapro MK17 | | | |
| class: diving system basic | | | |
| location: LDC | | | |

| tests/measurements | unit | min | max | actual | result |
|--|------|-----|------|--------|--------|
| visual test (0 = ok input mask: (0 = classic, > 0 = extended/list...)) | | | 0 | 0 | OK |
| High-pressure leak test, test time: 0,5 min, test pressure: bar | bar | -5 | | 0 | OK |
| safety valve opening pressure | bar | 12 | 21 | 17,2 | OK |
| static medium pressure at 200 bar cylinder pressure | bar | 8 | 10,5 | 9,5 | OK |
| MP leakage after 0,5 min at 200 bar 1mt. 1 0=rel. 1=abs. pulse | bar | | 10,5 | 9,6 | OK |
| pressure comparison at 200 bar | bar | -10 | 10 | -7 | OK |
| pressure comparison at 60 bar | bar | -10 | 10 | -8 | OK |
| pressure release of test equipment (HP, MP and LP) | | | | 0 | OK |

test executed: 11.02.2026 23:21
 by: Daniel Kristensen
 test signed: 11.02.2026 23:21
 by: Daniel Kristensen

result:
device ready for use

LabNet V: 2025.12.2.0

next test on: 11.02.2027