

<b>workshop:</b> DS BERGEN AS		person:	Daniel Kristensen
street:	Storebotn 55G	phone:	91649162
place:	5309 Kløppetø	fax:	
<b>customer:</b> Sanba Marin		email:	Daniel@dsbergen.no
street: Røtingavegen 4		person:	An-Magritt
place: 5216 Søre Øyane		phone:	91841270
		fax:	
		email:	Foxinspector@sanbamarin.no
<b>device data:</b>	<b>deadlines:</b>	<b>device-info:</b>	<b>service:</b>
device no: 2312056	1 y test 11.12.2026		- 1 year service
	1 y srv 11.12.2026		- 10 year service
	10 y srv 11.12.2035		- 15 year service
	15 y srv 11.12.2040		- cleaning and disinfection
type: Poseidon Cyklon			
class: diving system basic			
location: Foxinspector			

New bailout 1.stage without gauge and hoses.

tests/measurements	unit	min	max	actual	result
visual test (0 = ok) input mask: (0 = classic, > 0 = extended/list...)			0	0	OK
HP leakage at max pressure after 0,5 min	bar	-5		-1	OK
demand valve opening pressure	bar	12	21	18	OK
static medium pressure at 150 bar cylinder pressure	bar	8	10,5	10,1	OK
MP leakage after 0,5 min at 190 bar 1mt. 1 0=rel. 1=abs. pulse	bar		10,5	10,2	OK
pressure comparison at 190 bar	bar	-10	10	0	OK
pressure comparison at 60 bar	bar	-10	10	0	OK
pressure release of test equipment (HP, MP and LP)				0	OK

test executed: 11.12.2025 14:40  
 by: Daniel Kristensen

result:

test signed: 11.12.2025 14:40  
 by: Daniel Kristensen

device ready for use

Lab.Net Profi V: 2024.0.0.0

next test on: 11.12.2026