

# CYLINDER HYDRO TEST

Certificate no: DSC-2026-000408

Service date: 22.02.2026

Valid until: 22.02.2027

Result: **Approved**

## Equipment details

Customer: Sjøentreprenøren AS  
Producer: Faber  
Serial no: 15/1912/082  
Service interval: 24 months

Location: Mjø  
Model: Diving cylinder  
Build year: 2015

## Data

Cylinder type: Steel                      Color: Yellow                      Cylinder volume: 10.0  
Oxygen cleaned: No                      Working pressure (bar): 300                      Test pressure (bar): 490                      Application type: Diving  
Test facility number: D79                      Weight (kg): 15.00                      Thread type: M25x2                      Hydro tested: 02/2026

## Exterior

Heat damage	Pass	Weight	Pass
Repainted	No	Line corrosion	Pass
Hammer test	Pass	Exterior condition	Pass
Odor	Pass	Minimum wall thickness	Pass
Dent or bulge	Pass	Value: 5.9	
		Exterior approved	Pass

## Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Value: 0	
Sealing surface damaged	Pass	Interior approved	Pass

## Pressure testing

Water temperature	Pass	PU (test pressure reached)	Pass
Water fill (in)	Pass	PU% (percentage of test pressure)	-
Water drain (out)	Pass	Pressure testing approved	Pass

## Valve

Overhauled	Yes	Filling connection thread	Pass
Valve/cylinder thread	Pass		



# CYLINDER HYDRO TEST

Certificate no: DSC-2026-000408

Service date: 22.02.2026

Valid until: 22.02.2027

Result: **Approved**

## General

Repairs on cylinder

No

Cylinder and valve approved

Pass

## Technician

Serviced by: Daniel Kristensen

Signature

*Daniel Kristensen*

