

# 1.STAGE BAILOUT

Certificate no: DSC-2026-000541

Service date: 11.03.2026

Valid until: 11.03.2027

Result: **Approved**

## Equipment details

Customer: Valen marina AS  
Producer: Poseidon  
Serial no: 2312092  
Service interval: 12 months

Location: Valen Marina  
Model: Cyklon  
Build year: 2023

## NOTE

Tested with Labtech

This is a certificate confirmation, the documentation has a separate file.

## Technician

Serviced by: Daniel Kristensen

Signature



<b>workshop:</b> DS BERGEN AS		person:	Daniel Kristensen
street: Storebotn 55G		phone:	91649162
place: 5309 Kleppestø		fax:	
		email:	Daniel@dsbergen.no
<b>customer:</b> Valen Marina AS		person:	Ryder Hunt
street: Døsjevegen 66		phone:	
place: Kolltveit		fax:	
		email:	ryder.hunt@valenmarina.no
<b>device data:</b>	<b>deadlines:</b>	<b>device-info:</b>	<b>service:</b>
device no: 2312092	1 y test 11.03.2027		- 1 year service
	1 y srv 11.03.2027		- cleaning and
	10 y srv 27.09.2034		disinfection
	15 y srv 27.09.2039		
type: Poseidon Cyklon			
class: diving system basic			
location: Falken			

1.trinn bailout m/ manometer

tests/measurements	unit	min	max	actual	result
visual test (0 = ok) input mask: (0 = classic, > 0 = extended/list...)			0	0	OK
High-pressure leak test, test time: 0,5 min, test pressure: bar	bar	-5		-1	OK
safety valve opening pressure	bar	12	21	18,4	OK
static medium pressure at 150 bar cylinder pressure	bar	8	10,5	8,5	OK
MP leakage after 0,5 min at 190 bar lmt. 1 0=rel.1=abs. pulse	bar		10,5	9,5	OK
pressure comparison at 190 bar	bar	-10	10	-5	OK
pressure comparison at 60 bar	bar	-10	10	-3	OK
pressure release of test equipment (HP, MP and LP)				0	OK

test executed: 11.03.2026 21:09  
 by: Daniel Kristensen  
 test signed: 11.03.2026 21:09  
 by: Daniel Kristensen

result:  
 device ready for use

LabNet V: 2025.12.2.0

next test on: 11.03.2027