

CYLINDER HYDRO TEST

Certificate no: DSC-2026-000599

Service date: 06.04.2026

Valid until: 06.03.2035

Result: **Approved**

Equipment details

Customer: Sjøentreprenøren AS
Producer: SEFIC
Serial no: 25AG062 021UT
Service interval: 24 months

Location: Alu kontainer
Model: 5L cylinder
Build year: 2025

Data

Cylinder type: Oxygen SSteel Color: white Cylinder volume: 5.0
Oxygen cleaned: Yes Working pressure (bar): 230 Test pressure (bar): 345 Application type: Surface
Test facility number: - Weight (kg): 7.40 Thread type: 25E Hydro tested: 03/2025

Exterior

Heat damage	Pass	Weight	Pass
Repainted	No	Line corrosion	Pass
Hammer test	Pass	Exterior condition	Pass
Odor	Pass	Minimum wall thickness	Pass
Dent or bulge	Pass	Value: 3.5	
		Exterior approved	Pass

Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Value: 0	
Sealing surface damaged	Pass	Interior approved	Pass

Pressure testing

Water temperature	Pass	PU (test pressure reached)	Pass
Water fill (in)	Pass	PU% (percentage of test pressure)	Pass
Water drain (out)	Pass	Pressure testing approved	Pass

Valve

Overhauled	-	Filling connection thread	Pass
Valve/cylinder thread	Pass		



CYLINDER HYDRO TEST

Certificate no: DSC-2026-000599

Service date: 06.04.2026

Valid until: 06.03.2035

Result: **Approved**

General

Repairs on cylinder

- Cylinder and valve approved

Pass

Technician

Notes: New Oxygen cylinder 5L, Only VP and Oxygen cleaning

Serviced by: Daniel Kristensen

Signature

Daniel Kristensen

