

HYPERBARIC CHAMBER SERVICE CERTIFICATE

DSC-2026-000615

Service date: 08.04.2026

Valid to: 08.04.2027

Result: **Approved**

Equipment details

Customer: Valen marina AS
Producer: Draeger
Serial no: 1244
Service interval: 12 months

Location: Chamber Container
Model: Chamber
Build year: 1982

Pressure

| | | |
|---------------------------------|-------|------|
| Pressure reducing valve | — | Pass |
| Main chamber overpressure valve | 5.5 | Pass |
| Entry lock overpressure valve | — | - |
| Pipe maximum working pressure | 300.0 | Pass |

Pressure test
Pressure: — bar
Time: — min
Descent: — min
Ascent: 0 min

Hydro
Last hydrostatic test:
30.08.2023
Next hydrostatic test:
30.08.2033
Hydrotested: No
Testrange: —

Checklist

| | | | |
|--|------|----------------------------------|------|
| General condition | Pass | Communication – main chamber | Pass |
| Entry lock inlet valve | Pass | Communication – Entry lock | Pass |
| Entry lock outlet valve | Pass | Gasket – medical lock | Pass |
| Main chamber inlet valve | Pass | Gasket – Entry lock door | Pass |
| Main chamber outlet valve | Pass | Gasket – main chamber door | Pass |
| Depth alarm – audible signal DE-OX | Pass | Window/viewport 06/2023 | Pass |
| Depth gauge | Pass | Valves & Piping | Pass |
| High pressure gauge (HP) | Pass | Lightening | Pass |
| Low pressure gauge (LP) | Pass | Cameras | Pass |
| BIBS / O ₂ mask see bibs certificate | Pass | Surface treatment inside/outside | Pass |
| LP bank | - | Equalizer | Pass |
| HP Bank Composite 8x50L 200Bar | Pass | Drainage | Pass |
| O ₂ needle valves internal / external | Pass | | |

Technician

Serviced by: Daniel Kristensen

Signature

