

CYLINDER INSPECTION CERTIFICATE

Certificate no: DSC-2026-000633

Service date: 09.04.2026

Valid until: 09.04.2027

Result: **Approved**

Equipment details

Customer: Valen marina AS
Producer: Carbotainer
Serial no: 068987
Service interval: 24 months

Location: Chamber Container
Model: Cylinder Composite
Build year: 2023

Data

Cylinder type: Composite Color: grey Cylinder volume: 50.0
Oxygen cleaned: No Working pressure (bar): 200 Test pressure (bar): 300 Application type: Surface
Test facility number: - Weight (kg): 23.10 Thread type: 25E Hydro tested: 02/2023

Exterior

Heat damage	Pass	Weight	Pass
Repainted	No	Line corrosion	Pass
Hammer test	Pass	Exterior condition	Pass
Odor	Pass	Minimum wall thickness	Pass
Dent or bulge	Pass	Exterior approved	Pass

Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Interior approved	Pass
Sealing surface damaged	Pass		

Valve

Overhauled	No	Filling connection thread	Pass
Valve/cylinder thread	Pass		

General

Repairs on cylinder	No	Cylinder and valve approved	Pass
---------------------	----	-----------------------------	------

Technician



CYLINDER INSPECTION CERTIFICATE

Certificate no: DSC-2026-000633

Service date: 09.04.2026

Valid until: 09.04.2027

Result: **Approved**

Serviced by: Daniel Kristensen

Signature

Daniel Kristensen

