

# CYLINDER INSPECTION CERTIFICATE

Certificate no: DSC-2026-000637

Service date: 09.04.2026

Valid until: 09.04.2027

Result: **Approved**

## Equipment details

Customer: Valen marina AS  
Producer: Carbotainer  
Serial no: 072158  
Service interval: 24 months

Location: Chamber Container  
Model: Cylinder Composite  
Build year: 2023

## Data

Cylinder type: Composite                      Color: grey                      Cylinder volume: 50.0  
Oxygen cleaned: No                      Working pressure (bar): 200                      Test pressure (bar): 300                      Application type: Surface  
Test facility number: -                      Weight (kg): 23.50                      Thread type: 25E                      Hydro tested: 02/2023

## Exterior

Heat damage	Pass	Weight	Pass
Repainted	No	Line corrosion	Pass
Hammer test	Pass	Exterior condition	Pass
Odor	Pass	Minimum wall thickness	Pass
Dent or bulge	Pass	Exterior approved	Pass

## Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Interior approved	Pass
Sealing surface damaged	Pass		

## Valve

Overhauled	No	Filling connection thread	Pass
Valve/cylinder thread	Pass		

## General

Repairs on cylinder	No	Cylinder and valve approved	Pass
---------------------	----	-----------------------------	------

## Technician



# CYLINDER INSPECTION CERTIFICATE

Certificate no: DSC-2026-000637

Service date: 09.04.2026

Valid until: 09.04.2027

Result: **Approved**

Serviced by: Daniel Kristensen

Signature

*Daniel Kristensen*

