

Equipment details

Customer: Bergen Brannvesen AS
Producer: Luxfer
Serial no: M057555
Service interval: 24 months
Location: Bergen Brannvesen
Model: Vest flaske
Build year: 2023

Data

Cylinder type: Alu
Oxygen cleaned: -
Test facility number: D79
Color: Black
Working pressure (bar): 300
Weight (kg): -
Cylinder volume: 0.4
Test pressure (bar): 450
Thread type: -
Application type: Diving
Hydro tested: -

Exterior

Heat damage	-	Weight	-
Repainted	-	Line corrosion	-
Hammer test	-	Exterior condition	-
Odor	-	Minimum wall thickness	-
Dent or bulge	-	Exterior approved	-

Interior

Interpreted (thread verification)	Fail	Amount of loose material	Fail
Threads approved	Fail	Pitting corrosion depth	Fail
Crack formation	Fail	Interior approved	Fail
Sealing surface damaged	Fail		

Pressure testing

Water temperature	-	PU (test pressure reached)	-
Water fill (in)	-	PU% (percentage of test pressure)	-
Water drain (out)	-	Pressure testing approved	-

Valve

Overhauled	-	Filling connection thread	-
Valve/cylinder thread	-		



General

Repairs on cylinder - Cylinder and valve approved -

Technician

Notes: Kondemnert inkludert kran, Ikke mulig å åpne uten stor kraft. Floodet

Serviced by: Daniel Kristensen

Signature

Daniel Kristensen

