

Equipment details

Customer: Bergen Brannvesen AS	Location: Bergen Brannvesen
Producer: Luxfer	Model: Vest flaske
Serial no: M057565	Build year: 2023
Service interval: 24 months	

Data

Cylinder type: Alu	Color: Black	Cylinder volume: 0.4
Oxygen cleaned: No	Working pressure (bar): 300	Test pressure (bar): 450
Test facility number: D79	Weight (kg): -	Thread type: M18
		Application type: Diving
		Hydro tested: 05/2026

Exterior

Heat damage	Pass	Weight	Pass
Repainted	No	Line corrosion	Pass
Hammer test	Pass	Exterior condition	Pass
Odor	Pass	Minimum wall thickness	Pass
Dent or bulge	Pass	Exterior approved	Pass

Interior

Interpreted (thread verification)	Pass	Amount of loose material	Pass
Threads approved	Pass	Pitting corrosion depth	Pass
Crack formation	Pass	Interior approved	Pass
Sealing surface damaged	Pass		

Pressure testing

Water temperature	Pass	PU (test pressure reached)	Pass
Water fill (in)	Pass	PU% (percentage of test pressure)	Pass
Water drain (out)	Pass	Pressure testing approved	Pass

Valve

Overhauled	No	Filling connection thread	Pass
Valve/cylinder thread	Pass		



Certificate no: DSC-2026-000699

Valid until: 20.05.2028

Result: **Approved**

Repairs on cylinder

No

Cylinder and valve approved

Pass

Serviced by: Daniel Kristensen

Signature

Donald K. Benson

