

Equipment details

Customer: Bergen Brannvesen AS
Producer: Interspiro
Serial no: W06507 / 54
Service interval: 24 months
Location: Bergen Brannvesen
Model: Cylinder
Build year: 2022

Data

Cylinder type: Steel
Oxygen cleaned: -
Test facility number: D79
Color: white
Working pressure (bar): 300
Weight (kg): 5.60
Cylinder volume: 4.0
Test pressure (bar): 450
Thread type: M18
Application type: Diving
Hydro tested: 05/2026

Exterior

|               |      |                        |      |
|---------------|------|------------------------|------|
| Heat damage   | Pass | Weight                 | Pass |
| Repainted     | No   | Line corrosion         | Pass |
| Hammer test   | Pass | Exterior condition     | Pass |
| Odor          | Pass | Minimum wall thickness | Pass |
| Dent or bulge | Pass | Exterior approved      | Pass |

Interior

|                                   |      |                          |      |
|-----------------------------------|------|--------------------------|------|
| Interpreted (thread verification) | Pass | Amount of loose material | Pass |
| Threads approved                  | Pass | Pitting corrosion depth  | Pass |
| Crack formation                   | Pass | Interior approved        | Pass |
| Sealing surface damaged           | Pass |                          |      |

Pressure testing

|                   |      |                                   |      |
|-------------------|------|-----------------------------------|------|
| Water temperature | Pass | PU (test pressure reached)        | Pass |
| Water fill (in)   | Pass | PU% (percentage of test pressure) | Pass |
| Water drain (out) | Pass | Pressure testing approved         | Pass |

Valve

|                       |      |                           |      |
|-----------------------|------|---------------------------|------|
| Overhauled            | No   | Filling connection thread | Pass |
| Valve/cylinder thread | Pass |                           |      |



Certificate no: DSC-2026-000725

Valid until: 27.05.2028

Result: **Approved**

## Repairs on cylinder

No

Cylinder and valve approved

Pass

Serviced by: Daniel Kristensen

**Signature**

Donald K. Benson

